




KM822 KM1022 KM1222

Wiring Diagrams

1 Phase

Wiring Diagram
Automatic Kiln
Models:
KM822 / KM1022 / KM1222
1-Zone
1-Phase 2-Wire + G



3 Phase

Wiring Diagram
Automatic Kiln
Models:
KM822 / KM1022 / KM1222
1-Zone
3-Phase 3-Wire + G

